

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2867	DATE	June 14 <sup>th</sup> , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The fuel tank may have a welding fault on the lid of the mounting hole for the suction jet pump. Due to driving vibration etc., this may lead to the formation of cracks at the weld seam, where the fuel may leak from.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-1A16	BMW 116i	2011 - 2014	20,455
	BMW 120i		3,291
		TOTAL	23,746