

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2868	DATE	June 17 <sup>th</sup> , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The printed circuit boards used for a control unit of an electrical drive motor are not properly plated because the plating process is inadequate. Therefore, the control unit would detect an error and warning message of the drive system is displayed, in the worst case, there is a possibility that the vehicle switch off the high voltage power then loss of drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-1Z06	BMW i3	2018	33
AZZ-1Z00			1
		TOTAL	34