

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2869	DATE	June 17 th , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Moisture can enter into the crack on the plastic element of the blow-by heater of the engine ventilation, which was caused by inappropriate production. If the crack is expanded by freezing-up, and further moisture enter into the heater element, short circuit may occur followed by overheat of the heater may occur. When keep driving under such condition, warning lamp lights on and in an extreme case, the plastic material may smolder. In worst case, fire in engine compartment or vehicle cannot be excluded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-UF30	BMW 130i	2005	74
ABA-VB23	BMW 323i	2005	1705
ABA-VB25	BMW 325i	2005	2038
ABA-VB30	BMW 330i	2004 – 2005	1294
ABA-VD30	BMW 330Xi	2005	60
ABA-VS25	BMW 325i Touring	2005	394
ABA-NE25	BMW 525i	2005	2118
ABA-NE30	BMW 530i	2005	1132
ABA-NL25	BMW 525i Touring	2005	519
ABA-NL30	BMW 530i Touring	2005	305
GH-EH30	BMW 630i	2004 – 2005	80
ABA-EH30		2005	134
		TOTAL	9,853