VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4519	DATE	June 20, 2019
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	conductive contaminants. If th	cation of internal gears the grease sump. Th ads, oil contained in the ixed with wear debris in the vehicle continues in the motor terminal and sh	s of the electric parking brake rough repeatedly driving and e grease collected in the sump the motor, thereby generating service in this condition, such ort-circuit the motor, causing

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-JF1	「N-BOX SLASH」	2014~2018	36,939
DBA-JF2		2014~2018	6,480
		TOTAL	43,419