## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	4521	DATE	Jun.26.2019
MANUFACTURER	ТОУОТА		
DESCRIPTION OF DEFECT	In the subject hybrid vehicles, due to improper water proof structure of the cowl louver installed rear of the engine compartment, there is a possibility that water could drip onto the engine under heavy rain conditions, causing the water to enter in the cylinder bore of the engine through the injector installation area. If this were to occur, the connecting rods can damage, leading to abnormal noise, and in the worst case, the engine could be damaged.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-NHP170G	[TOYOTA SIENTA]	2015-2018	137,016
		TOTAL	137,016