

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4523	DATE	June 26, 2019
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	<p>With the internal-combustion engine forklift vehicles, there are cases that the welding penetration of the fuel tank and hydraulic oil tank are insufficient due to incorrect welding.</p> <p>There is a possibility that the welding may get cracked and lead to leakage of fuel or hydraulic oil if large load may be applied repeatedly to the portion.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-8FD40	TOYOTA GENE0	2014 – 2017	247
YDN-8FD50		2014 – 2017	164
YDN-8FD80		2014 – 2017	92
EBT-8FG40		2014 – 2017	43
EBT-8FG50		2014 – 2017	16
		TOTAL	562