## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No. GAI-2865 DATE Jun. 26, 2019   MANUFACTURER Audi   (Japanese Importer: Audi Japan KK)   DESCRIPTION The auxiliary heater element in the air conditioner may fail in very rare cases due to an electrical connector which has not been plugged in correctly. This may lead to smoulder damage or even fire   DEFECT The connector on the heater element must be checked on the affected vehicles.				-	
MANUFACTURER(Japanese Importer: Audi Japan KK)DESCRIPTION OF DEFECTThe auxiliary heater element in the air conditioner may fail in very rare cases due to an electrical connector which has not been plugged in correctly. This may lead to smoulder damage or even fire	CAMPAIGN No.	GAI-2865	DATE	Jun. 26, 2019	
Image: Construction of the second state(Japanese Importer: Audi Japan KK)Image: Description of DEFECTThe auxiliary heater element in the air conditioner may fail in very rare cases due to an electrical connector which has not been plugged in correctly. This may lead to smoulder damage or even fire		Audi			
DESCRIPTION OF DEFECT an electrical connector which has not been plugged in correctly. This may lead to smoulder damage or even fire	MANUFACIUKEK	(Japano	ese Importer: Audi Japan KK)		
The connector on the neutron element must be enceded on the affected venicles.		an electrical connector which has not been plugged in correctly. This may lead to			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-4GCHJS	Audi A6 Hybrid	2014	8
		Total	8