## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	GAI-2871	DATE	Jun. 26, 2019	
MANUFACTURER	Audi			
MANUFACTURER	(Japanese Importer: Audi Japan KK)			
	Fluctuations in the tightening torque of the bolts securing the fuel rail. Individual bolts			
DESCRIPTION OF	may loosen over time.			
DEFECT				
	The bolted connections for the fuel rail must be tightened.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8WCVN	Audi A4 1.4T	2017-2019	1,073
		Total	1,073