

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4518	DATE	June 27, 2019
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	In the affected "under cover", due to improper maintenance of the tool to join the bracket, adhesive force of some parts is diminishing. As a result, the applied vibration while driving and the corrosion developed by the road salt may gradually divide the joint area, leading to making a noise. In the worst case, the bracket may fall off, obstructing traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ND5RC	Mazda「Roadster」	2015	1,231
		Total	1,231