

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2878	DATE	June 27,2019
MANUFACTURER	HONDA AUTOMOBILE (THAILAND) CO., LTD.		
DESCRIPTION OF DEFECT	Driver's SRS airbag inflator for field servicing may be subject to deterioration of gas generating propellant through repeated fluctuations in ambient temperature and humidity. Deteriorated gas generating propellant can cause abnormal rise in inflator internal pressure during the airbag deployment whereby the inflator container could be broken.		

Applicable to driver's SRS airbag inflator shipped as a field servicing part so far as it is possible to trace the vehicle to which it may have been fitted.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-GD6	「FIT ARIA」	2003	3
LA-GD8		2002~2003	4
DBA-GD8		2006	1
DBA-GD9		2008	1
		TOTAL	9