

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 2881	DATE	XX June, 2019
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that during production of the vehicle front axle assembly the electrical power steering wiring harness can become trapped. During operation and over the vehicle's lifetime, the insulation of the trapped wiring harness may be damaged.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-G2H40A	Panamera Turbo	2017	3
ABA-G2H40AX			1
ABA-G2J29A	Panamera 4S	2018	8
ABA-G2J29AX			1
ABA-G2J40A	Panamera Turbo	2018	14
ABA-G2J40AX			2
ALA-G2J40A	Panamera Turbo S	2018	53
ALA-G2J40AX			6
3BA-G2K40A	Panamera GTS	2019	6
		Total	94