

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4525	DATE	Jul.11 2019
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In the relevant large-sized buses, since the fixing method of the wiring for the optionally provided front door glass heater is inappropriate, the wiring at the arm (upper horizontal bar) may be locally bent when the door is opened and closed. Continued use of the vehicle may cause repeated bending of the wiring when the door is opened and closed, resulting in an open circuit in the wiring and occurrence of smoke.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-MS96JP	「FUSO AERO ACE」	2007～2010	939
	「FUSO AERO QUEEN」	2007～2010	256
LKG-MS96VP	「FUSO AERO ACE」	2010～2012	300
	「FUSO AERO QUEEN」	2010～2012	83
QRG-MS96VP	「FUSO AERO ACE」	2012～2015	1,489
	「FUSO AERO QUEEN」	2012～2015	208
QTG-MS96VP	「FUSO AERO ACE」	2015～2017	1,518
	「FUSO AERO QUEEN」	2015～2017	460
2TG-MS06GP	「FUSO AERO ACE」	2017～2019	881
	「FUSO AERO QUEEN」	2017～2019	167
LDG-MM96FH	「FUSO AERO ACE」	2011～2012	4
PDG-MM96FH		2008～2011	198
QDG-MM96FH		2012～2014	21
QDG-MM97FH		2014～2017	58
SDG-MM96FH		2011～2012	28
TDG-MM96FH		2012～2014	113
TDG-MM97FH		2014～2017	312
PDG-AM96FH		「SPACEARROW A」	2008～2011
BKG-AS96JP	2007～2010		53
LKG-AS96VP	「SPACEWING A」	2008～2010	6
	「SPACEARROW A」	2010～2011	11
	「SPACEWING A」	2010～2011	4
TOTAL			7,120