

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4533	DATE	Jul. 11. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain light-duty trucks with mixer specifications, due to the improper shape of the vacuum hose for the brake, the hose concerned may be bent by the routing variation. Therefore, it may take time to supply negative pressure, the brake warning light is illuminated early and the warning buzzer sounds, resulting the braking force to be less effective.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
2KG-XZU700M	[HINO Dutro]	2017~2019	50	
		TOTAL	50	