

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-2885	Date	July, 11, 2019
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	<p>A concern has been identified on 2001 to 2008 Model Year Jaguar X-TYPE and 2002 to 2008 Model Year Jaguar S-TYPE vehicles where dealers are unable to correctly adjust the headlamp beam on certain vehicles. The investigation identified during headlamp beam pattern adjustment, the adjuster link arm may break. Once the adjuster link arm is broken, the beam pattern cannot be aligned and contravenes the United Nations Economic Commission for Europe (UNECE) 98.01 Supplement 1 regulation.</p> <p>These vehicles were subject to previous recall campaign J021 (Gai-1809) in Japan.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
GH-J51YA	X-TYPE 2.0 V6	2001.25 - 2008	1,781
ABA-J51YB	X-TYPE 2.0 V6 Estate		1,648
GH-J51XA	X-TYPE 2.5 V6	2001.25 – 2008	1,545
ABA-J51XB	X-TYPE 2.5 V6 SE X-TYPE 2.5 V6 Sport X-TYPE 2.5 V6 Estate		567
GH-J51WA	X-TYPE 3.0 V6 SE		659
ABA-J51WB	X-TYPE 3.0 V6 SE X-TYPE 3.0 V6 Sport X-TYPE 3.0 V6 Sovereign	2001.25 - 2008	96
GH-J01JC	S-TYPE 2.5 V6	2002.5 - 2008	906
GH-J01FC	S-TYPE 3.0 V6	2002.5 - 2008	837
CBA-J01FD			648
GH-J01HC	S-TYPE 4.2 V8	2002.5 - 2008	100
CBA-J01HD			30
GH-J011C	S-TYPE R	2002.5 - 2008	143
CBA-J011D			20
		Total	8,980

(JIS A4 size)