

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2889	DATE	July 11, 2019
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	In the manufacturing process of the shift pedal, there are some which are not securely fixed because the crimping process of the tip of the shift pedal is inappropriate. As a result, there is a risk that the tip of the shift pedal may drop off, making it impossible to shift. Check the condition of crimping on the tip of the shift pedal for all vehicles, and if the crimping is not sufficient, the official Ducati dealer will replace the gearshift pedal. This will be performed free of charge		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-MA02	MONSTER 1200 MONSTER 1200S	2017-2019	161
2BL-MH00	MONSTER 821	2018	107
2BL-VA01	SUPERSPORT SUPERSPORT S	2017-2019	407
		TOTAL	675