

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4539	DATE	July 18 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the exhaust pipe of the medium duty truck, the bellows portion may be resonated by the engine revolutions because of the improper structure of the flexible pipe's bellows. Due to the resonance, inner parts of the flexible pipe rub against each other. If the driver continues using the vehicle without repair, these parts may wear out and get holes, possibly leading to exhaust gas leakage.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FRR90S1 TKG-FRR90S2 TKG-FRR90T2	[FORWARD]	2014-2017	49,999
SKG-FSR90S2 SKG-FSR90T2 SPG-FSR90S2 SPG-FSR90T2		2014-2017	3,481
LKG-FTR90S2 LKG-FTR90T2 LPG-FTR90S2 LPG-FTR90T2		2014-2017	3,639
		TOTAL	57,119

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Exhaust Pipe	8-98276939-0	2017-2018	3
	8-98276940-0	2016-2017	3
	8-98276941-0	2018	1
	8-98276945-0	2016-2018	39
		TOTAL	46