

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4540	DATE	July 19, 2019
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>There is a problem of strength poverty with the mounting bracket of the LPG vaporizer with the Komatsu's LPG engine forklifts. Under such a circumstance, if the engine is kept running with hydraulic operation at the low idle condition, it generates the vibration. Then the crack may form at the bracket.</p> <p>Therefore, if the vehicle is kept being used under such a circumstance, the bracket may be broken, and LPG vaporizer may fall. Then the stress will provide to the fuel pipes and in the worst case, the fuel pipes may be broken, and the LPG may leak and ignite.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SM220	—	2006-2008	10
M224	—	2005-2008	207
M225	—	2005-2008	11
SM225	—	2005-2008	103
M226	—	2005-2008	18
SM226	—	2006-2008	8
M227	—	2005-2008	5
M232	—	2005-2006	8
M233	—	2005-2006	2
TOTAL			372