

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4544	DATE	Aug. 1. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain starters of light duty trucks, due to the improper insulation inspection method in the manufacturing process, starters installing the brush holder part with faulty insulation may have been put on the market. Therefore, smoke may be emitted when the starter is operated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-XZC605M	[HINO Dutro]	2019	2
2RG-XZU605M		2019	1
2RG-XZU645M		2019	1
2RG-XZU655M		2019	1
2KG-XZU675M		2019	1
2KG-XZU695M		2019	1
2RG-XZU710M		2019	1
2PG-XZU722M		2019	1
2KG-XZU732M		2019	1
		TOTAL	10