

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4545	DATE	Aug. 1. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain mechanical automatic transmissions of middle duty trucks and buses, because the setting of the program inputting equipment for the gear positioning sensor is inappropriate, temperature correction values may not be input in the gear positioning sensor. Therefore, when driving on an uphill road etc. and the temperature of the sensor rises high, the sensor may become unable to output correctly, resulting the warning light to illuminate and the gear unable to be shifted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FC2ABA	[HINO Ranger]	2019~2019	23
2KG-FC2ABG			
2KG-FD2ABA		2019~2019	14
2KG-FD2ABG			
2KG-GD2ABG			
2DG-RR2AJDA	[HINO Melpha]	2019~2019	4
		TOTAL	42