

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2898	DATE	2/August/2019
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Wrong upper Control Arm has been assembled on the left side. This may cause asymmetric steering behavior, noise from front suspension if contact between tire and wheel housing, ESC risk of false interventions. The corrective action is to exchange the left upper Control Arm.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[V60]	2019	2
TOTAL			2