VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2907	DATE	Oct,21, 2019	
MANUFACTURER	DUCATI MOTOR HOLDING SpA			
	(Japanese Importer: DUCATI JAPAN Ltd.)			
DESCRIPTION OF DEFECT	In the ventilation circuit of fuel tank cap, the capacity of ventilation circuit			
	may not be sufficient, and the pressure in the fuel tank may rise when the			
	temperature of fuel tank rises due to the influence of the outside air			
	temperature and engine temperature.			
	Therefore, if the fuel tank cap is opened while the pressure in the fuel			
	tank is rising, there is a risk that the fuel may jet out. The official Ducati dealer will modify the fuel tank cap ventilation circuit			
	and insert a caution page	ind insert a caution page in the owner's manual.		
	This will be performed free of charge			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-DA00J	Panigale V4/V4S	2018-2019	460
2BL-DA00J	Panigale V4 Speciale	2018-2019	69
2BL-DA04	Panigale V4R	2018-2019	54
		TOTAL	583