

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2909	DATE	Aug.28.2019
MANUFACTURER	NUMMI (TOYOTA)		
DESCRIPTION OF DEFECT	In the front passenger air bag inflator of the subject vehicles, due to improper study of deployment characteristics, air bag internal pressure may rise differently than expected during activation of the air bag under high temperature conditions. In this condition, the airbag could be torn or the bag plate could be damaged, causing the air bag not to properly inflate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-ZZE136	[VOLTZ]	2002-2004	106
TA-ZZE137			49
UA-ZZE138			53
		TOTAL	208