

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4553	DATE	Aug.29, 2019
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>The drive shaft dust boot may have the insufficient strength in the weld line portion, due to the improper temperature control in the manufacturing process. Due to this, the dust boot may be cracked, resulting in the grease leakage.</p> <p>In the worst case, it may become impossible to drive the vehicle.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-MK53S	SPACIA	2018	5,821
DBA-MH35S	WAGON R		539
DAA-MH55S			3,739
DBA-HA36S			ALTO
HBD-HA36V	233		
DBA-HE33S	ALTO LAPIN		1,607
EBD-DA16T	CARRY		2,070
EBD-DR16T	NT100 CLIPPER		246
DAA-MM53S	FLAIR WAGON		547

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-MJ55S	FLAIR	2018	549
DBA-HB36S	CAROL		329
EBD-DG16T	SCRUM		61
EBD-DS16T	MINICAB		174
		TOTAL	17,541