VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

			Domestic Import Vehicles		
CAMPAIGN No.	Gai-2872	DATE	2019/9/3		
MANUFACTURE	Daimler AG				
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)				
DESCRIPTION OF DEFECT	On certain C-Class, E-Class and SLK vehicles (204, 207, 212, 172 platforms) with 4-cylinder gasoline engine (M271 EVO) the camshaft adjuster function could be impaired due to wear of mechanical components. First consequence of increased wear is a noticeable noise during engine start. Continued increasing wear may cause delayed engine starts which would illuminate the check engine warning lamp (MIL) and subsequently deactivate the heating of the catalytic converter. As a result, legal emission standards might not be met.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-204049	C180 -	2012	1138
		2013	4
DBA-204249	C180CGI Stationwagon	2012	797
		2013	4
DBA-204349	C180 Coupe	2012	973
		2013	1
DBA-204048	C200CGI	2010	2430
		2011	3863
		2012	7223
		2013	2
DBA-204248	C200CGI Station Wagon	2010	1055
		2011	2365
		2012	4484
		2013	4
DBA-204047	C250CGI	2010	451
		2011	228
		2012	463
		2013	5

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-204247	C250CGI Station Wagon	2010	275
		2011	142
		2012	317
		2013	1
DBA-204347	- C250 Coupe	2012	592
		2013	2
-204347-		2012	3
		2013	1
DBA-212047C		2010	1389
	E250CGI -	2011	2430
		2012	2114
		2013	3
DBA-212247C	E250CGI Station Wagon	2010	357
		2011	947
		2012	952
DBA-207347	E250CGI Coupe -	2010	671
		2011	774
		2012	390
		2013	1
DBA-172448	SLK200	2012	1589
		2013	5
		TOTAL	38,445