

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	外-2904	Date	Sep 4, 2019
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	A spring installed in brake pedal may be fractured and fail switching brake lump. Then, drivers can't show intention of braking activation/deactivation correctly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-LTE	「926M」	2017-2018	22
YDR-KTG	「930M」	2017-2018	18
YDS-J3R	「938M」	2017-2018	37
		TOTAL	77