

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2914	DATE	September 4 th , 2019
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	Due to an insufficient manufacturing process, oil residue might be possible on the nuts, with which the left and right tail lights are attached to the vehicle body. This could cause damage on the tail light holder. As a result, the tail light could become shaky, which would not comply with the Japanese safety regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3R30	B3S Biturbo Touring	2019	2
		TOTAL	2