VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

		-	
CAMPAIGN NO.	4560	DATE	September 5 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the heavy duty truck that runs on compressed natural gas (CNG), the fuel pipe may get cracks because the rigidity of the bracket used for fixing the main stop valve is insufficient, and also the instruction for mounting the gas container is inappropriate. Therefore, due to incidents such as vibration while the vehicle in motion, the cracks may get worse, possibly leading to fuel leakage.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
QFG-CYJ78B	[GIGA]	2017-2018	8
QFG-CYL78B		2016-2018	8
		TOTAL	16