

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4561	DATE	Aug.9 2019
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>For the accelerator pedal of the wheel crane, found that rubber part of the stopper bolt for shock absorbing purpose might become sticky by hydrolysis phenomenon due to inappropriate selection of rubber material.</p> <p>Therefore, the accelerator pedal might not return immediately when pressing the pedal fully as the accelerator pedal stuck to the stopper bolt.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
UDS-KRC011	KR-25H	2013~2016	1831	
WDR-KRC013	KRM-13H	2013~2017	1441	
YDS-KRC017	KR-25H	2016~2019	556	
YDS-KRC016	KR-50H	2016~2019	515	
UDS-KRC012	KR-75H	2013~2016	447	
YDS-KRC018	KR-80H	2017~2019	347	
UDS-KRC014	KRM-20H	2014~2016	280	
YDR-KRC020	KRM-13H	2017~2019	212	
UDS-KRC015	KRM-35H	2014~2016	183	
YDS-KRC019	KRM-20H	2017~2019	93	
TOTAL			5905	