

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4569	DATE	Sep. 18. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain engine control computers, due to the inappropriate rotational speed control in starting, the oil pump performance varies and the amount of engine oil is small, which may disable the oil pressure to be generated. Therefore, if the oil pressure warning light is illuminated and the idle rotation is continued, the bearing portion may be damaged and abnormal noise may be made, resulting the engine to stop operating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FH1AGA	[HINO Profia]	2017~2019	287
2PG-FH1AGG			
2KG-FN1AGA		2017~2019	1,126
2PG-FN1AGA			
2PG-FN1AGG			
2KG-FN1AJA			
2KG-FN1AJG		2017~2019	1,113
2PG-FN1AJA			
2PG-FN1AJG			
2PG-FQ1AJG			
2PG-FQ1AJJ		2017~2019	811
2PG-FR1AGA			
2PG-FR1AHA		2017~2019	108
2PG-FR1AHG			
2PG-FR1AHJ			
2RG-FR1AHA			
2RG-FR1AHG			
2RG-FR1AHJ			
2SG-FR1AHH			
2SG-FR1AHS			
2DG-FR1AJA		2017~2019	746
2KG-FR1AJA			
2PG-FR1AJA			
2PG-FR1AJG			
2RG-FR1AJG			
2PG-FS1AGA		2017~2019	2,905

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2KG-FS1AHA	[HINO Profia]	2017~2019	693	
2PG-FS1AHA				
2PG-FS1AHG				
2PG-FS1AHJ				
2RG-FS1AHA				
2RG-FS1AHG				
2RG-FS1AHJ				
2KG-FS1AJA		2017~2019	826	
2PG-FS1AJA		2017~2019	10,792	
2PG-FW1AHG				
2PG-FW1AHJ				
2RG-FW1AHG				
2RG-FW1AHJ				
2SG-FW1AHH				
2SG-FW1AHS				
2PG-FW1AJG				2017~2019
2PG-FW1AJJ		2019	1	
2RG-FW1AJG				
2RG-FW1AJJ				
2PG-SH1ADGG				
2PG-SH1AGGG				2018~2019
2PG-SH1AHGG		2018	1	
2PG-SH1ALGG		2018~2019	2	
			TOTAL	24,602