

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4568	DATE	Sep.20 2019
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>Some steering knuckles for crane chassis have insufficient thickness at the top of the knuckle because the drawing instructions for the mold are inappropriate.</p> <p>Therefore, if it is used for a long period of time, a crack will occur at the top of the knuckle, and in the worst case, normal steering may not be possible.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
KA5160	—	2015~2018	38	
KA6360	—	2017~2018	8	
JDS-KRC006	KR-70H	2009	1	
TOTAL			47	