

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4570	DATE	Sep.26.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In a rear axle of four-wheel vehicles, due to an improper material of the oil seal, there is a possibility that the lip of the oil seal could wear abnormally while driving under low temperature conditions. If this were to occur, the differential oil may leak, and in the worst case, the leaked oil could be attached to the brake shoes, resulting in the decrease of braking force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBE-NCP55V	[SUCCEED] [PROBOX]	2014	482
DBE-NCP165V		2014-2019	58,944
DBE-NCP165M	[FAMILIA VAN]	2018-2019	245
		TOTAL	59,671