

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4572	DATE	Oct,3, 2019
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Some of the left front drive shaft may have insufficient strength due to the improper quenching treatment. Due to this, the drive shaft may break if the vehicle is being used continuously and it may become impossible to drive the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-HA36S	ALTO	2015	835
HBD-HA36V			77
DBA-HB36S	CAROL		9
		TOTAL	921