

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4579	DATE	October 3, 2019
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	The stay holding the horn to the body lacks strength. Due to vibrations generated at certain engine speeds, the stay may be loaded and cracked. If the vehicle continues in service in such a condition, the crack can grow and eventually fracture the stay whereby the horn could be fallen off the body in the very worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-PD11	「CRF450L」	2018	243
		TOTAL	243