

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 5 8 0	DATE	O c t . 1 5 . 2 0 1 9
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to an inappropriate program in the engine control unit, when the throttle is opened slightly from the idling state, the air-fuel mixture which will be taken into the combustion chamber may become thin. Therefore, in the worst case scenario, the air-fuel mixture may lead to abnormal combustion, and as a result, an engine stall may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-DG31J	SEROW XT250	2018~2019	4,277
2BK-DG32J	t r i c k e r XG250		1,090
		TOTAL	5,367