

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4576	DATE	Oct.17, 2019
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to improper assigned bending value of Positive Crankcase Ventilation valve, which is a part of Blow-by gas ventilation system, the crankcase lacks its durability for certain vehicles. If the connection part fractures, engine oil may flow into combustion chamber and burn, exceeding amount of smoke may be released from muffler, and in the worst case, engine may stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GK2	「IMPREZA」	2016 ~ 2018	1,707
DBA-GK3		2016 ~ 2018	1,382
DBA-GK6		2016 ~ 2018	3,367
DBA-GK7		2016 ~ 2018	5,844
DBA-GT2		2016 ~ 2018	10,052
DBA-GT6		2016 ~ 2018	10,631
DBA-GT3	「IMPREZA」 「XV」	2016 ~ 2018	12,568
DBA-GT7		2016 ~ 2018	37,676
		TOTAL	83,227