

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4577	DATE	Oct.17, 2019
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	For certain vehicles, improper control programmed by a control program of Engine Control Unit activates when engine stops, causing excessive conduction. As the result, it may increase the internal temperature of ignition coil, which leads short circuit, fuse blown, and in the worst case, engine stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GK2	「IMPREZA」	2016 ~ 2019	2,856
DBA-GK3		2016 ~ 2019	2,278
DBA-GK6		2016 ~ 2019	4,616
DBA-GK7		2016 ~ 2019	7,955
DBA-GT2		2016 ~ 2019	17,328
DBA-GT6		2016 ~ 2019	14,390
DBA-GT3	「IMPREZA」 「XV」	2016 ~ 2019	26,768
DBA-GT7		2016 ~ 2019	61,276
		TOTAL	137,467