VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	4558	DATE	October 18. 2019		
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.				
DESCRIPTION OF DEFECT	In the power transmission device for the agricultural tractors, the structure of the main transmission first speed gear is inappropriate, which may result in insufficient lubrication and poor lubrication. Therefore, if it continues to be used as it is, the first gear of the main transmission and the shaft may be seized, and in the worst case, the tractor cannot run.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED			ER OF ICLE
_	「YT357」	2018~2019		1,249	
			TOTAL	1,249	