

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4592	DATE	Oct. 24. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In the integrated controller in the bus, the control program for the door anti-trap function is inappropriate. Consequently, if the accelerator pedal is depressed as the door is closing, the door anti-trap system may be deactivated, causing the passengers to get trapped in the door.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-KR290J4	[HINO Rainbow]	2019	1
2DG-KV290N3 2KG-KV290N3	[HINO Blue Ribbon]	2019	3
		TOTAL	4