## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	4590	DATE	October 25 ,2019	
MANUFACTURER	NIPPON TREX CO., LTD.			
DESCRIPTION OF DEFECT	Regarding the spare tire mounting device for coil transporting semi trailer, strength of the connection part between chassis flame mounting part and hanger bracket is insufficient because of inappropriate strength design.  Therefore, cracks may occur due to the burden at the time of running, and in the worst case, there is possibility that the said part breaks and the spare tire mounting device will fall, and it may be an obstruct of other trafic.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PFV335AB	_	2013~2014	5
PFV335AD	_	2014	12
PFV335AE	_	2014	3
PFV335AF	_	2014	2
PFV335AG	_	2015	1
PFV335AH	_	2015	13
PFV335AJ	_	2017~2018	5
PFV335AK	_	2017	1
PFV335AL	_	2017	1
PFV335AN	_	2017	4
PFV335AP	_	2018	5
PFV335AR	_	2018	1
PFV335AU	_	2019	4
		TOTAL	57