## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	4596	DATE	Oct.30.2019		
MANUFACTURER	ΤΟΥΟΤΑ				
DESCRIPTION OF DEFECT	In the engine control computer of the subject vehicles, due to improper programming of charging control, there is a possibility that, when the long period of idling is frequently repeated, a battery could be deteriorated abnormally. If this were to occur, the engine will not re-start after an idling stop.				

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DBA-AGH30W	[ALPHARD] [VELLFIRE]	2017-2019	2,604	idling stop and start system
DBA-AGH35W	[,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		10,604	vehicles
DBA-GGH30W			7,645	
DBA-GGH35W			2,980	
L		TOTAL		23,833