VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2942	DATE	Oct. 30, 2019	
MANUFACTURER	Audi			
MANUFACTURER	(Japanese Importer: Audi Japan KK)			
	A failure of the front LED turn signal may not always be detected in certain			
DESCRIPTION	circumstances due to insufficient sensitivity of the function monitoring.			
OF DEFECT				
	A software update of the onboa	ard supply control unit must b	e carried out.	

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8UCULB	Q3 2.0Tq 132kw	2015 – 2018	2,128
ABA-8UCULC	Q3 2.0Tq 162kw	2015 – 2017	179
ABA-8UCZD	Q3 1.4T	2015 – 2018	1,885
ABA-8UCZGF	RSQ3	2015 – 2018	431
		Total	4,623