

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2944	DATE	Oct. 30,2019
MANUFACTURER	DAIHATSU (PT. Astra Daihatsu Motor)		
DESCRIPTION OF DEFECT	Due to improper production control of the connecting rod of engine, there may be crack inside the rod. In the worst case, the connecting rod may break under high load driving conditions and cause the vehicle to be inoperable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBF-S402M	TOWN ACE/LITE ACE	2018-2019	8,067
DBF-S412M			4,023
DBF-S402U			3,149
DBF-S412U			1,232
		TOTAL	16,471