

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	4585	DATE	October. 31. 2019
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	<p>In the engine of a rotary snowplow, the engine controller wiring instruction is inappropriate. There are some which are in contact with engine equipment. Therefore, the wiring is damaged by the traveling vibration, and the warning lamp is turned on by short-circuiting. In the worst case, the engine may stop.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-R03E	「HTR308」	2016~2018 R03E-0002~ R03E-0114	112
TOTAL			112

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.