

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|------|-----------------|
| CAMPAIGN No. | 4598 | DATE | October 31,2019 |
| MANUFACTURER | MITSUBISHI MOTORS CORPORATION | | |
| DESCRIPTION OF DEFECT | Concerning to the control harness of the turbocharged engine, due to a cable routing is inappropriate, the harness may contact with the intercooler case by vibration from driving. For this, there is a possibility that a cover of an electric wire in the harness could be rubbed away so that short circuit may occur. In a worst case, an engine may stall while driving. | | |

| T Y P E | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|-----------------|---------------------|-------------------|
| 4AA-B35W | 「eK」 | 2019 | 2,041 |
| 4AA-B38W | | 2019 | 1,108 |
| 4AA-B45W | 「DAYZ」 | 2019 | 4,399 |
| 4AA-B48W | | 2019 | 827 |
| | | TOTAL | 8,375 |