

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	4599	DATE	October 31, 2019	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	<p>With regards to the spare tire carrier for heavy-duty tractors, when the retainer fixing nuts are tightened with designated torque, the bolt may stretch by generated tension load because of the insufficient strength of the retainer fixing bolts welded to the spare tire carrier bracket. Thus, the bolt may fracture by vehicle vibration, in the worst case scenario, the winch fixing screws may be broken and detached from the bracket, after which the winch might drop along with the spare tire.</p>			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-GK5AAB	Quon	2018 - 2019	8	
2PG-GK5AAD			577	
2PG-GK5AAE			125	
2PG-GK5AAK			2	
		TOTAL	712	