

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4601	DATE	November 7,2019
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	On the brake vacuum pump which generates negative pressure in the brake booster, water may intrude into the pump while in use due to an inappropriate waterproof structure. This may cause corrosion on the inside of the pump, leading to the deterioration of pump performance and triggering the brake warning lamp illumination along with the buzzer. In the worst case, the operating force of a brake pedal may be increased and the braking distance may be extended.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-HA3W	「i-MiEV」	2009～2012	9,563
ZAA-HA4W		2013～2018	1,991
ZAA-HD4W		2018～2019	97
ZAB-U67V	「MINICAB-MiEV」	2011～2012	4,833
ZAB-U68V		2013～2019	2,278
ZAB-U68T		2013～2016	1,037
		TOTAL	19,799