

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4600	DATE	8 , 11 , 2019
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Since water entry into the transmission of the shovel loader was not sufficiently evaluated, if much water is poured over the wheels or the sides of engine hood, the water may enter the transmission oil through the transmission breather. As a result, the water in the transmission evaporates, enters the starting motor, and causes rust, then the engine becomes disabled to start in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-WA120	「WA470-7」	2012 - 2016	56
YDS-WA129	「WA470-8」	2015 - 2018	25
		TOTAL	81