

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4604	DATE	Nov. 15, 2019
MANUFACTURER	SHO-SHIN Co, Ltd.		
DESCRIPTION OF DEFECT	Since the waterproof structure of the engine upper part of the crop-dusting vehicles is inappropriate, water at the time of car wash, etc. or the like may enter the plug hole. Therefore, the spark plug is rapidly cooled by water at the time of car wash, etc. or the like, and in the worst case, the insulator of the plug is cracked to cause a misfire, which may cause unstable engine rotation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBT-J4	「3S-VE642」	2016-2016	39
		2016-2019	102
		TOTAL	141