

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4613	DATE	November 19, 2019
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	Due to the inappropriate installation layout design of garbage compactors, some of them do not have enough space between the tipping cylinder of the compactor body and its differential gear case; therefore gear case can hit the tipping cylinder when the rear axle bounces up to the highest and lubricant can leak from the cracked differential gear case. In the worst case, the vehicle can be unable to travel due to seizure of the differential gear.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-NPR75N	「ELF」	2011	1
TKG-NPR85YN		2015~2017	10
TPG-NPR85AN		2019	1
2PG-NPR88YN		2018	2
		TOTAL	14