

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4609	DATE	Nov.20.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the electric circuit of the hazard lamps, due to insufficient capacity of the fuse, if the hazard lamps are frequently activated, the fuse could deteriorate by current flowing during operation of the hazard lamps causing the fuse to blow, resulting in the hazard lamps and turn signal lamps becoming inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
SKG-XZB60 SPG-XZB60	[TOYOTA COASTER]	2017-2019	906	
SKG-XZB70 SPG-XZB70 SDG-XZB70			4,135	
SKG-XZB60V	[TOYOTA COASTER BIG VAN]		121	
SKG-XZB70V			53	
SKG-XZB60M SPG-XZB60M	[HINO LIESSE □]		403	
SKG-XZB70M SPG-XZB70M SDG-XZB70M			3,148	
SKG-XZB60Y	[HINO LIESSE □ BIG VAN]		21	
SKG-XZB70Y			46	
			TOTAL	8,833